Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	3	("6974447" "6846305" "6280431").pn.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2007/09/30 17:08
S2	3	("6974447" "6846305" "6280431").pn.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2007/08/10 13:03
S3	1069	604/403.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:08
S4	333	S3 and (port or nozzle)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:13
S5	258	S4 and (flange saddle reinforce attach seal)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:15
S6	5	S5 and (attach\$4 near (flange or saddle))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:13
S7	0	604/408.ccls	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:12

			,	Y		
S8	847	604/408.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:13
S9	379	S8 and (port or nozzle)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:13
S10		S9 and (attach\$4 near (flange or saddle))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:14
S11	411	604/410.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:13
S12		S11 and (flange saddle reinforce attach seal)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:14
S13	0	S12 and (attach\$4 near (flange or saddle))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:14
S14	578	604/411.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:15

, ,	·					
S15	441	S14 and (flange saddle reinforce attach seal)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:14
S16	8	S15 and (attach\$4 near (flange or saddle))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:16
S17	637	604/415.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:15
S18	443	S17 and (flange saddle reinforce attach seal)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:15
S19	2	S18 and (attach\$4 near (flange or saddle))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:18
S20	0	young-harvey.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:18
S21	0	young-theodore-harvey.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR <sub>.</sub>	ON	2007/09/30 17:18

S22	68	young-harvey\$10.in.	US-PGPUB;	OR	ON	2007/09/30 17:19
		young-narvey\$10.iii.	USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OK	·	2007/03/30 17.19
S23	16	S22 and (flange or port or container)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/30 17:19
S24	6	(US-20060282061-\$ or US-20060276769-\$ or US-20050059951-\$ or US-20070027437-\$).did. or (US-5514123-\$ or US-5334180-\$). did.	US-PGPUB; USPAT	OR	OFF	2007/09/30 17:21
S25	2	((flexible) and (container or bag) and (port) and (nozzle) and (diameter) and (attach attachment attach\$4 join weld seal heat) and (flange or saddle or reinforc\$5)). clm.	US-PGPUB	OR	ON	2007/09/30 17:22